



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
September 6, 2007

Supervisor DDZ

Mine Name: Deer Trail Mine
Operator Name: Unico, Inc

Permit number: M/031/003
Inspection Date: August 28, 2007
Time: 2:30 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Charlie Greenwell
Mine Status: Active

Weather: Clear

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine inspection while in the area.

Inspection Summary:

Mining related activities have been confined to the permitted/bonded area.

During this inspection, the new facilities were toured. The mill building is near completion and systems were being tested/checked for leaks. The operator has made significant progress in cleaning up the area, consolidating the 'bone yard' and removing trash/debris from the site. Areas where old equipment and materials were previously scattered have been cleaned up and reclaimed.

The operator also indicated that the response to Division comments for the reclamation cost estimate for the proposed second mill building would be completed in the next couple of days and will be submitted to the Division by September 7, 2007.

Photos were taken.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M031-Piute\M0310003-Unico\inspections\insp-08282007.doc